


Option 1 - 32" High-Tensile (HT) woven wire with HT upper wires and offset "hot" wires



Click on the products and photos below to view on our website.

www.premier1supplies.com

800-282-6631 • Washington, IA



To install

1. Set and brace all end, corner and curve posts.
2. Stretch a GreenCote barbed wire at soil level to use as a "straight-edge" for installing the line posts.
3. Drive or hand-set the line posts.
4. Attach the barbed wire to the posts.
5. Unroll the woven wire. Strain it with our strainer clamps. Staple woven wire to the posts.
6. Strain and attach 2 HT smooth wires above the woven wire.
7. Attach offset wires.
8. Install a cut-out switch at an end post to allow turning off the power to the lower wire.
9. Connect all insulated wires to the energizer or cut-out switch.
10. Connect all noninsulated wires and/or woven wire to a ground rod.

Fence diagram

Product Name	Item
A. Battery, Plug-in or Solar Energizers	
B. Ground Rod, 6' x 5/8", 6 lb.....	#151000
Stainless Clamp, 0.10 lb.....	#151800
C. 5-Light Tester, 0.24 lb.....	#134100
D. Surge Protector, 0.20 lb.....	#156500
E. Insulated Cable	
F. Warning Sign, 0.06 lb.....	#346000
G. Cut-Out Switch, 0.32 lb.....	#333000
H. SupaTube for Hi-Tensile, 5", 0.10 lb.....	#360500
I. SupaTube for Hi-Tensile, 20", 0.20 lb.....	#362000
J. PI 20 Terminal Insulator, 0.10 lb.....	#369000
K. SupaTube Staples, 2", 1 lb.....	#360000
L. HT Wire Barbed Staples, 1.6", 1 lb.....	#360200
M. TwistLink, 12.5 gauge, 13", 0.10 lb.....	#336500
N. Round In-Line Strainer, 0.46 lb.....	#330100
O. HT Wire Dispenser, 24 lb.....	#402000
P. GreenCote HT Woven, 330', 115 lb.....	#411000

Product Name	Item
Q. HT Smooth Wire, 2000', 52 lb.....	#301200
R. GreenCote HT Sm Wire, 2100', 55 lb.....	#301210
S. GreenCote Barbed Wire, 660', 48 lb.....	#301400
T. Manual Joint Clamp, 0.08 lb.....	#337000
U. Gripple, barbed, 0.10 lb.....	#336820

Items not shown

Product Name	Item
Digital Voltmeter, 0.48 lb.....	#132000
Round Strainer Handle, 2 lb.....	#408200
Galv. Steel T Post, 6', 9 lb.....	#327600
PI 500 Steel Post Insulator, 0.10 lb.....	#380000
SupaTube for Hi-Tensile, 10", 0.20 lb.....	#361000
SupaTube for Hi-Tensile, 48", 0.40 lb.....	#364800
Gripple, medium, 0.06 lb.....	#336800
Speed Brace, (2 pack), 2.90 lb.....	#336840
Gripple Tensioning Tool, 1.90 lb.....	#336830
HT Woven Wire 8/32/9, 330', 115 lb.....	#411400



Q. Galvanized HT Smooth Wire
R. GreenCote HT Smooth Wire



S. Barbed Wire



T. Manual Joint Clamp



U. Gripple Barbed

