


Semi-Permanent Rope Fence up to 5 strands

Click on the products and photos below to view on our website.



www.premier1supplies.com

800-282-6631 • Washington, IA



C. 5-Light Tester



D. Insulated Cable



F. Conductor



G. Galv. Steel T Post



H. Premier Combo Ins.



I. T Post Safety Cap



J. Notched PI 21in Ins.



K. Premier Hot Top Ins.



L. 3. RopeLink 2.6

To install

Tools: Driver for wood and steel posts, hammer, screwdriver, cutter for rope and wire, battery drill and our driver to install insulators on wood posts.

Time: About 600 ft in 3 hours after end, corner and line posts are installed.

Skill: No special skills. Set steel end and corner posts 20-35 ft apart. If using more than 2 strands, wood and corners are advised 42" to 48" deep in firm soil.

Fence diagram

Product Name	Item
A. Energizers	
B. Galv. Rod, 6' x 5/8" , 6 lb.....	#151000
Galv. Rod, 3' x 1/2" , 2.10 lb.....	#151200
Stainless Clamp , 0.10 lb.....	#151800
C. 5-Light Tester , 0.30 lb.....	#200006
D. Insulated Cable	
E. Warning Sign , 0.06 lb.....	#346000
F. IntelliRope PE 4.5, 660' , 5 lb.....	#245100
IntelliRope PE 4.5, 1320' , 10 lb...	#245200
IntelliRope PE 6.0, 660' , 8.20 lb..	#256900
IntelliRope PE 6.0, 1320' , 18 lb...	#256910

Product Name	Item
G. Galv. Steel T Post , 6', 9 lb.....	#327600
H. Premier Combo Ins. , 0.10 lb.....	#380321
I. T Post Safety Cap , 0.06 lb.....	#381010
J. PI 21in Notched Ins. , 0.08 lb.....	#369200
K. Premier Hot Top , 0.20 lb.....	#381000
L. P Spring Combination	
1. PI 21 Terminal Ins. , 0.08 lb.....	#369100
2. P Spring , SS, 0.30 lb.....	#255010
3. RopeLink 2.6 , 0.10 lb.....	#256210

- L. 1. [PI 21 Terminal Insulator](#)
- 2. [P Spring](#)
- 3. [RopeLink 2.6](#)